

<b>1 – 20 Old Market Square</b>
<b>Summary of Progress - 24/04/19</b>
➤ Scaffolding 100% complete
➤ Hoist erected
➤ Main roof & Tank Room Roofs 90% complete
➤ Brickwork and Concrete Repairs in Progress and at Circa 20% Overall
➤ CCTV Drainage Surveys Completed and Reports Issued
➤ Fire Stopping Works Underway and at circa 50% overall. No Access Areas being worked on by the RLO Team
➤ Window Renewals – Internal Property surveys ongoing and design in progress
➤ Cavity Wall Inspections 100% complete
➤ Front Doors currently being Manufactured. Awaiting Firm Delivery Dates

<b>35 – 60 Old Market Square</b>
<b>Summary of Progress - 10/04/19</b>
➤ Scaffolding 100% complete
➤ Hoist erected
➤ Main roof & Tank Room Roofs 90% complete
➤ Brickwork and Concrete Repairs in Progress and at Circa 20% Overall
➤ CCTV Drainage Surveys Completed and Reports Issued
➤ Fire Stopping Works Underway and at circa 50% overall. No Access Areas being worked on by the RLO Team
➤ Window Renewals – Internal Property surveys ongoing and design in progress
➤ Cavity Wall Inspections 100% complete
➤ Front Doors currently being Manufactured. Awaiting Firm Delivery Dates



1 – 63 Pelter Street
Summary of Progress - 24/04/19
➤ Scaffolding 100% complete
➤ Hoist erected
➤ Main roof 95% complete
➤ Brickwork and Concrete Repairs in Progress and at Circa 5% Overall
➤ CCTV Drainage Surveys Completed
➤ Fire Stopping Works Underway and at circa 90% overall. No Access Areas being worked on by the Project RLO Team
➤ Window Overhauls – In Progress and at circa 40% Overall
➤ Cavity Wall Inspections 100% complete
➤ Front Doors currently being installed & 75% Complete overall.

64 – 86 Hackney Road
Summary of Progress - 24/04/19
➤ Scaffolding 100% complete
➤ Hoist erected
➤ Main roof 30% complete
➤ Brickwork and Concrete Repairs in Progress and at Circa 5% Overall
➤ CCTV Drainage Surveys Completed
➤ Fire Stopping Works Underway and at circa 90% overall. No Access Areas being worked on by the Project RLO Team
➤ Window Overhauls – In Progress and at circa 20% Overall
➤ Cavity Wall Inspections 100% complete
➤ Front Doors currently being installed & 20% Complete overall.